



Technical Service Bulletin

Technical Service Bulletin: tsb103054

Released Date: 24-Sep-2008

Lubricating Oil Pump Procedure, Multiple Section Revisions

Lubricating Oil Pump Procedure, Multiple Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 007-031 (Lubricating Oil Pump) in Bulletin 3666239, Signature™, ISX, and QSX15 Service Manual, to include instructions to reuse the external idler gear capscrew.

This capscrew is **not** listed for sale in the lubricating oil pump option. To obtain a replacement the capscrew, the complete lubricating oil pump option **must** be purchased.

Related Procedures

10-007-031-tr
(/qs3/pubsys2/xml/en/procedures/10/10-007-031-tr.html)

Lubricating Oil Pump
(/qs3/pubsys2/xml/en/procedures/10/10-007-031-tr.html)

Last Modified: 24-Sep-2008