



Technical Service Bulletin

Technical Service Bulletin: tsb103247	Released Date: 16-Feb-2009
Fault Code 259, Major Revision	

Fault Code 259, Major Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic introduces major revisions to Fault Code 259.
--

Fuel Shutoff Valve

Last Modified: 16-Feb-2009
