



Technical Service Bulletin

Technical Service Bulletin: tsb103650	Released Date: 16-Dec-2009
Fault Code 434, Guided Step 4C Revision	

Fault Code 434, Guided Step 4C Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Fault Code 434, Unswitched Battery Supply Circuit, in the 'Action' section in Guided Step 4C , to revise the pin numbers listed for exclusion in the short circuit check.

Unswitched Battery Supply Circuit

Last Modified: 16-Dec-2009
