



Technical Service Bulletin

Technical Service Bulletin: tsb103845

Released Date: 02-Jun-2009

Crankshaft Procedure, Clean and Inspect for Reuse Section Revision

Crankshaft Procedure, Clean and Inspect for Reuse Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Topics revises Procedure 001-016 in Section 1 to add the following statement:

Inspect the crankshaft for dynamic balancing marks. One or more of the crankshaft counterweights will contain a drilled hole or drilled start point indicating that the crankshaft has been balanced. NOTE – this applies to engines built March 2009 or later **only**.

This will allow for an easy check of the crankshaft to make sure it is balanced.

Related Procedures

10-001-016-tr
(/qs3/pubsys2/xml/en/procedures/10/10-001-016-tr.html)

(/qs3/pubsys2/xml/en/procedures/10/10-001-016-tr.html)

Last Modified: 02-Jun-2009