



Technical Service Bulletin

Technical Service Bulletin: tsb104008	Released Date: 03-Dec-2009
Symptom Trees t021 (Coolant Loss - Internal) and t025 (Coolant in the Lubricating Oil), Cause Revisions	

Symptom Trees t021 (Coolant Loss - Internal) and t025 (Coolant in the Lubricating Oil), Cause Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Symptom Trees t021 (Coolant Loss - Internal) and t025 (Coolant in the Lubricating Oil) in Section TS of the Signature™, ISX, and QSX15 Service Manual, Bulletin 3666239.

The cause descriptions for injector sleeve is leaking (t021 and t025) and the first investigated instance of coolant in the lubricating oil (t025) have been revised.

Coolant Loss - Internal Coolant in the Lubricating Oil

Last Modified: 03-Dec-2009
