



Technical Service Bulletin

Technical Service Bulletin: TSB130004

Released Date: 18-Jan-2013

Updated Cylinder Block Cleaning and Inspection Process

Updated Cylinder Block Cleaning and Inspection Process

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces changes to Procedure 001-026 (Cylinder Block). The changes include the creation and addition of a standardized cylinder block clean and inspect process. For information on the changes to this service procedure, refer to the list below for the appropriate manual.

- Reference the following procedure in the Signature, ISX , and QSX15 Service Manual, Bulletin 3666239. Refer to Procedure 001-026 in Section 1.
(/qs3/pubsys2/xml/en/procedures/10/10-001-026-tr.html)
- Reference the following procedure in the ISX CM2250 Service Manual, Bulletin 4022250. Refer to Procedure 001-026 in Section 1.
(/qs3/pubsys2/xml/en/procedures/132/132-001-026-tr-mixar5.html)
- Reference the following procedure in the QSX15 CM2250 ECF Service Manual, Bulletin 2883557. Refer to Procedure 001-026 in Section 1.
(/qs3/pubsys2/xml/en/procedures/132/132-001-026-tr-vqxi6.html)
- Reference the following procedure in the PowerGen QSX15 CM2250 ECF Service Manual, Bulletin 4310661. Refer to Procedure 001-026 in Section 1.
(/qs3/pubsys2/xml/en/procedures/132/132-001-026-tr-vqyg5a.html)
- Reference the following procedure in the PowerGen QSX15 CM2250 Service Manual, Bulletin 4310664. Refer to Procedure 001-026 in Section 1.
(/qs3/pubsys2/xml/en/procedures/132/132-001-026-tr-vqyg5na.html)

Document History

Date	Details
2013-1-2	Module Created

