



Technical Service Bulletin: TSB150019

Released Date: 18-Feb-2015

New Rear Power Take Off (REPTO) Idler Shaft and Capscrew

New Rear Power Take Off (REPTO) Idler Shaft and Capscrew

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces the release of a new rear power take off (REPTO) idler shaft and REPTO idler shaft capscrew design.

Product Affected

- ISX15 (All Versions)
- QSX15 (All Versions)

Description of Change

The new REPTO idler shaft has a smaller thru-hole and does **not** require the use of a washer. The REPTO idler shaft capscrew has changed from a grade 8 to a grade 10.9.

Reason for Change

The new REPTO idler shaft distributes clamp load more evenly.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Part Structure

The existing REPTO idler shaft part numbers have been obsoleted and superseded by the new REPTO idler shaft part numbers. The new parts are backward compatible.

Table 1: REPTO Idler Shaft and REPTO Idler Shaft Capscrew Part Numbers

Part Description	Obsolete Part Number	New Part Number
Idler Shaft	3102457	3689402
Idler Shaft	3102458	3689403
Hex Screw	4330970	3689542
Plain Washer	4330971	Not Applicable

Part Disposition

Use existing part number inventory before using the new part number.

Production Status

Implemented for production at Jamestown Engine Plant. Engine serial number (ESN) first is 79797680. Engine build date is 5 December 2014.

Publications Affected

The Signature™, ISX, and QSX15 Service Manual, Bulletin Number 3666239, has been revised. Refer to Procedure 016-007 in Section 16. (/qs3/pubsys2/xml/en/procedures/10/10-016-007-tr.html)

The ISX15 CM2250 Service Manual, Bulletin Number 4022250, has been revised. Refer to Procedure 016-007 in Section 16. (/qs3/pubsys2/xml/en/procedures/132/132-016-007.html)

The QSX15 CM2350 X105 Service Manual, Bulletin Number 4332667, has been revised. Refer to Procedure 016-007 in Section 16. (/qs3/pubsys2/xml/en/procedures/250/250-016-007.html)

The ISX15 CM2350 X101 Service Manual, Bulletin Number 4310641, has been revised. Refer to Procedure 016-007 in Section 16. (/qs3/pubsys2/xml/en/procedures/173/173-016-007.html)

Document History

Date	Details
2015-2-17	Module Created

Last Modified: 18-Feb-2015
