



Technical Service Bulletin

Technical Service Bulletin: TSB180160

Released Date: 07-Nov-2018

Oversized Cylinder Head Gaskets

Oversized Cylinder Head Gaskets

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK23 CM500

Description of Change

This document announces the release of oversized cylinder head gaskets.

Reason for Change

The new oversize cylinder head gasket was released to improve cylinder block serviceability.

Service Instructions

Reference QSK23 CM500 Troubleshooting and Repair Manual, Bulletin 4021375. Refer to Procedure 001-026 in Section 1.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	New Part Number
0.4 mm [0.016 in] Oversize Cylinder Head Gasket	4097018

Part Compatibility

- New oversized cylinder head gaskets are **not** compatible with original production cylinder blocks.
- Cylinder block **must** be machined to accept oversized cylinder head gasket.

Associated Publications

Table 2, Publications Affected					
Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	Section
Service Manual	QSK23 CM500 Troubleshooting and Repair Manual	4021375	Cylinder Block	Reference Procedure 001-026	1

Document History

Date	Details
2018-11-7	Module Created

Last Modified: 07-Nov-2018