



Technical Service Bulletin: TSB180165

Released Date: 26-Nov-2018

Navistar® Aftertreatment Backpressure Diagnostic FC6786 on International HX520 and HX620 Chassis

Navistar® Aftertreatment Backpressure Diagnostic FC6786 on International HX520 and HX620 Chassis

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

Engines:

- X15 CM2350 X114B
- X15 CM2350 X116B

Original Equipment Manufacturer (OEM):

- Navistar®

Chassis:

- International®
 - Model
 - HX520
 - HX620

Issue

Symptom:

- Reduced engine power.
- Fault Code 6786.

Root Cause:

- Exhaust aftertreatment backpressure diagnostic that triggers Fault Code 6786 was found to be out of adjustment resulting in false occurrences of Fault Code 6786.

Verification

Verify repeated instances of Fault Code 6786 logging but aftertreatment and exhaust system are within specification and in normal working order.

Resolution

Calibrate electronic control module (ECM) with correct ECM calibration code. See Table 1 below.

Table 1, ECM Calibration Code with Revision

HD10001.15

HD10002.14

HD10005.14

HD10011.12

HD10012.12

HD10014.12

HD10030.12

HD10031.12

HD10032.12

HD10036.12

HD10037.12

HD10038.12

HD10048.11

HD10050.11

HD10054.11

HD10055.11

HD10056.11

HD10057.11

HD10058.11

HD10059.11

HD10060.11

HD10061.11

HD10062.11

HD10072.11

HD10073.11

HD10074.11

HD10075.11

HD10076.11

HD10077.11

HD10078.11

HD10079.11

HD10080.11

HD10087.11

HD10089.11

Table 1, ECM Calibration Code with Revision
HD10126.11
HD10127.11
HD10128.11
HD10129.11
HD10130.11
HD10131.11
HD10132.11
HD10133.11
HD10134.11
HD10144.11
HD10145.11
HD10146.11
HD10147.11
HD10148.11
HD10149.11
HD10150.11
HD10151.11
HD10152.11
HD10162.11
HD10164.11
HD10169.09
HD10170.09
HD10171.09
HD10172.09
HD10173.09
HD10174.09
HD10175.09
HD10176.09
HD10177.09
HD10178.09
HD10179.09
HD10180.09
HD10181.09
HD10182.09
HD10183.09
HD10184.09

Table 1, ECM Calibration Code with Revision
HD10185.08
HD10186.08
HD10199.08
HD10200.08
HD10201.08
HD10202.08
HD10203.08
HD10204.08
HD10205.08
HD10206.08
HD10207.08
HD10208.08
HD10209.09
HD10210.09
HD10211.09
HD10212.09
HD10213.09
HD10214.09
HD10215.09
HD10216.09
HD10217.08
HD10218.08
HD10221.05
HD10222.05
HD10223.05
HD10224.05
HD10225.05
HD10226.05
HD10227.05
HD10228.05
HD10229.05
HD10230.05
HD10231.05
HD10232.05
HD10233.05
HD10234.05

Table 1, ECM Calibration Code with Revision
HD10235.05
HD10236.05
HD10237.05
HD10238.05
HD10239.05
HD10240.05
HD10241.05
HD10242.05
HD10243.05
HD10244.05
HD10245.05
HD10246.05
HD10247.05
HD10248.05
HD10249.05
HD10250.05
HD10251.05
HD10252.05
HD10279.05
HD10280.05
HD10281.05
HD10282.05
HD10283.05
HD10284.05
HD10285.05
HD10286.05
HD10287.05
HD10288.05
HD10289.05
HD10290.05
HD10291.05
HD10292.05
HD10293.05
HD10294.05
HD10295.05
HD10296.05

Table 1, ECM Calibration Code with Revision
HD10297.05
HD10298.05
HD10299.05
HD10300.05
HD10301.05
HD10302.05
HD10303.05
HD10304.05
HD10305.05
HD10306.05
HD10309.05
HD10310.05
HD10313.05
HD10314.05
HD10317.05
HD10318.05
HD10321.05
HD10322.05
HD10325.05
HD10326.05
HD10329.05
HD10330.05
HD10331.05
HD10332.05
HD10333.05
HD10334.05
HD10335.05
HD10336.05
HD10337.05
HD10338.05
HD10008.16
HD10009.16
HD10024.14
HD10025.14
HD10043.14
HD10044.14

Table 1, ECM Calibration Code with Revision
HD10045.14
HD10091.13
HD10094.13
HD10097.13
HD10100.13
HD10103.13
HD10114.13
HD10115.13
HD10187.11
HD10188.11
HD10189.11
HD10190.11
HD10191.11
HD10192.11
HD10193.11
HD10194.11
HD10195.11
HD10196.11
HD10197.11
HD10198.11
HD10219.11
HD10220.11
HD10253.08
HD10254.08
HD10255.08
HD10256.08
HD10257.08
HD10258.08
HD10259.08
HD10260.08
HD10261.08
HD10262.08
HD10263.08
HD10264.08
HD10265.08
HD10266.08

Table 1, ECM Calibration Code with Revision
HD10267.08
HD10268.08
HD10269.08
HD10270.08
HD10271.08
HD10272.08
HD10273.08
HD10274.08
HD10275.08
HD10276.08
HD10277.08
HD10278.08
HD10339.08
HD10340.08
HD10341.02
HD10342.02

Document History

Date	Details
2018-11-20	Module Created