



Technical Service Bulletin

Technical Service Bulletin: TSB190017

Released Date: 11-Jun-2019

High Number of Inactive Counts of Fault Code 7125

High Number of Inactive Counts of Fault Code 7125

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- X12 CM2350 X119B
- X15 CM2350 X114B

Issue

- High number of inactive counts of FC7125

Root Cause:

- Engine control module (ECM) calibration code issue leading to FC7125 appearing after a power down.

Verification

- Verify if there are any performance or drivability issues with operator.
- Confirm multiple inactive counts of FC7125 are logged.

Resolution

If no performance or drivability issues are present, check the ECM Calibration Revisions page on QuickServe® Online (QSOL) for applicable fixes. Calibrate the ECM if necessary. See corresponding Service Manual. Reference Procedure 019-032 in Section 19.

Document History

Date	Details
2019-1-24	Module Created
2019-3-4	Non-Product Problem Solving (PPS)
2019-6-10	added ecm calibration steps

