



Technical Service Bulletin

Technical Service Bulletin: TSB190041

Released Date: 22-Mar-2019

Unable to Create Engine Control Module (ECM) Work Order Image Using INLINE 6 and J1708 Communication Protocol

Unable to Create Engine Control Module (ECM) Work Order Image Using INLINE 6 and J1708 Communication Protocol

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Products Affected

- B Gas Plus CM556
- C Gas Plus CM556
- ISB CM850
- ISBE CM800
- ISBe4 CM850
- ISC CM850
- ISL CM850
- ISLe4 CM850
- ISM CM570
- ISM CM570
- ISM CM870
- ISM CM875
- ISX CM570
- ISX CM870
- QSB3.9 30 CM550
- QSB4.5 30 CM550
- QSB5.9 30 CM550
- QSB5.9 44 CM550
- QSC8.3 CM554
- QSL9 CM554
- QSM11CM570
- QSX15 CM570

Issue

On engine programs that can use both J1708 and J1939 communication protocols, when trying to create a work order image with INSITE™ electronic service tool using J1708 protocol and INLINE™ 6 datalink adapter, the work order creation fails between 15 to 30% and error 10431 will be displayed.

Resolution

To create an engine control module (ECM) work order image, use the J1939 protocol with INLINE™ 6 datalink adapter, or use an INLINE™ 7 datalink adapter if available.

Document History

Date	Details
2019-3-19	Module Created

Last Modified: 22-Mar-2019
