



Technical Service Bulletin

Technical Service Bulletin: TSB200090

Released Date: 13-Jul-2020

New Rear Crankshaft Seal

New Rear Crankshaft Seal

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- K19
- K19 G Natural Gas
- KTA19 GC
- KTA19 G CMEICS K123

Issue

Symptom:

- Rear crankshaft seal leaks oil.

Root Cause:

- Rear crankshaft seal does not seal properly on the crankshaft.

Verification/Confirmation

Rear crankshaft leaks oil.

Resolution

For engines with dry flywheel housings leaking oil from rear crankshaft seal (PN 3160925), install new rear crankshaft seal (PN 4922217) for increased sealing performance.

Part Inventory Action

Rear crankshaft seal kit Part Number 4089902 is available for service.

Document History

Date	Details
2020-4-16	Module Created
2020-7-13	Non-Product Problem Solving (PPS)

Last Modified: 13-Jul-2020
