



Technical Service Bulletin: TSB220194

Released Date: 19-Sep-2022

Reducing Occurrences of Fault Code 197

Reducing Occurrences of Fault Code 197

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2450 X124B
- X15 CM2450 X134B

Issue Summary

Symptoms:

- Audible coolant level warning
- Light on screen with 'Low Coolant Level' message
- Active or inactive Fault Code 197

Root Cause:

- Coolant level fluctuations are higher than expected during normal engine operation triggering the Fault Code 197.

Verification

- Verify that Fault Code 197 is active or has more than one inactive count within the last 25 engine operating hours.
- Compare the ECM calibration code and revision number in the ECM to the ECM calibration code revision listed in the ECM calibration revision history for applicable changes.

Resolution

- A new ECM calibration code revision has been released that reduce occurrences of low coolant level fault code 197.
- If a calibration update for this fault code is available, the ECM calibration revision **must** be that revision or higher.

Document History

Date	Details
2022-9-19	Module Created

Last Modified: 19-Sep-2022
