



Technical Service Bulletin

Technical Service Bulletin: TSB230104

Released Date: 12-Nov-2024

Fault Code 2198 During Cummins® Electronic Service Tool VGT Hysteresis Test

Fault Code 2198 During Cummins® Electronic Service Tool VGT Hysteresis Test

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- B6.7 CM2350 B121B
- B6.7 CM2350 B135B
- B6.7 CM2350 B136C
- B6.7 CM2350 B148B
- B6.7 CM2350 B157C
- B6.7 CM2450 B155B
- ISB6.7 CM2350 B101
- ISB6.7 CM2350 B103
- ISB6.7 CM2350 B142
- ISL9 CM2350 L101
- ISL9 CM2350 L111
- ISL9 CM2350 L163B
- L9 CM2350 L116B
- L9 CM2350 L119B
- L9 CM2350 L120C
- L9 CM2350 L123B
- L9 CM2350 L129C
- L9 CM2350 L133C
- L9 CM2350 L148C
- L9 CM2450 L126B
- L9 CM2450 L127B
- L9 CM2450 L143C
- L9 CM2450 L149M
- L9 CM2450 L150M
- L9 CM2450 L151C
- L9 CM2450 L164C

- L9 CM2450 L165C
- L9 CM2450 L166C
- L9 CM3350 L139B
- X12 CM2350 X119B
- X12 CM2350 X144C
- X12 CM2450 X137B
- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2350 X125M
- X15 CM2350 X129B
- X15 CM2450 X124B
- X15 CM2450 X134B
- X15 CM2450 X142B

Issue Summary

Symptom:

- Fault Code 2198 is active during VGT Hysteresis Test with Cummins® Electronic Service Tool.

Root Cause:

- False occurrences of Fault Code 2198 during VGT Hysteresis Test.

Verification

- Review active and inactive fault codes with Cummins® electronic service tool or equivalent.
- Fault Code 2198 became active during the VGT Hysteresis Test.

Resolution

- If Fault Code 2198 becomes active during VGT Hysteresis test and is **not** accompanied by Fault Code 1894, no troubleshooting of Fault Code 2198 is required.

Document History

Date	Details
2023-5-11	Module Created
2024-11-12	Added X142B to Product Affected section.