



Technical Service Bulletin

Technical Service Bulletin: TSB230203

Released Date: 20-Oct-2023

New Upper Idler Gear Idler Shaft

New Upper Idler Gear Idler Shaft

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- ISX CM570
- ISX CM870
- ISX CM871
- ISX CM871 E
- QSX15 CM570

Description of Change

A new upper idler gear idler shaft has been released with a revised orientation indicator.

Reason for Change

A new idler shaft was released with reduced radial growth material properties because radial growth can prevent proper lash setting.

Service Instructions

See corresponding Service Manual. Refer to Procedure 001-088 in Section 1 for installing the idler shaft.

Service Parts

Service parts are offered. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Idler Shaft	3680239	Yes	Yes	3685252

Part Identification



Figure 1, Idler Shaft, Part Number 3680239, With "Top" Indicator.



Figure 2, Idler Shaft, Part Number 3685252, With Arrow Indicator.

Part Inventory Action

Use existing part number inventory before using the new part number.

Production Status

Implemented for new and ReCon® parts **only**.

Publications Affected

Table 3, Publications Affected

Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	Section
Service Manual	ISX CM570	3666239	Engine Base Timing	Refer to Procedure 001-088 (/qs3/pubsys2/xml/en/procedures/10/10-001-088.html)	1
	QSX15 CM570				
	ISX CM870				
	ISX CM871				
	ISX CM871 E				

Document History

Date	Details
2023-10-18	Module Created