



Technical Service Bulletin

Technical Service Bulletin: TSB240160

Released Date: 30-Aug-2024

New Piston Pin

New Piston Pin

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- ISX (All Versions)
- ISX15 (All Versions)
- X15 (All Versions)
- QSX15 (All Versions)

Description of Change

A new piston pin has been released with increased strength and pin joint durability.

Reason for Change

This piston pin was developed for use in engines with higher cylinder pressures.

Service Instructions

- The new piston pin is backwards compatible and intermixable with existing piston pin.
- X15 CM2450 X142B **must** use the new piston pin, Part Number 6382850.

Service Parts

Service parts are offered. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Piston Pin	3689296	Yes	Yes	6382850
Piston Kit	-	No	No	6502719
Piston Kit	-	No	No	6502720

Part Identification

The new piston pin has a smaller ID compared to the existing piston pin, as shown in Figure 1.



Figure 1, New Piston Pin (Top) vs. Existing Piston Pin (bottom).

Part Inventory Action

Use existing part number inventory before using the new part number.

Production Status

Implemented for production. See Table 2.

Table 2, Production Information		
ESN First	Build Date ¹	Plant
80607343	1 January 2023	Jamestown Engine Plant
¹ Engine build date can be found on the engine dataplate.		

Document History

Date	Details
2024-8-5	Module Created

