



Technical Service Bulletin

Technical Service Bulletin: TSB170026

Released Date: 17-Mar-2017

Engine Cleaning

Engine Cleaning

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- ISX12 CM2350 X102
- ISX12/ISX11.9 CM2250
- ISX15 CM2250
- ISX15 CM2350 X101
- X15 CM2350 X114B
- X15 CM2350 X116B

Description of Change

Engine Steam Cleaning procedure has been updated to cover a broader range of engine cleaning practices and is now called Engine Cleaning.

Reason for Change

Updated procedure has precautionary statements to cover appropriate cleaning practices. Cummins Inc. has received malfunctioned parts that were the result of soap entering the air intake system. Do **not** directly spray or allow soap, solvent, or water to enter any passages, ports, or cowlings that lead to air intake system.

Publications Affected

Table 1, Publications Affected				
Manual Type	Engine	Bulletin Number	Procedure Title	Procedure
Service Manual	ISX12 CM2250	2883445	Engine Cleaning	Refer to Procedure 000-009 (/qs3/pubsys2/xml/en/procedures/99/99-000-009.html)
	ISX12 CM2350	4310646		
	ISX15 CM2250	4022250		
	ISX15 CM2350	4310641		
	X15 X114B	5411181		
	X15 X116B	5411186		
Operation and Maintenance Manual	ISX12 CM2250	2883444		
	ISX12 CM2350	4310645		
	ISX15 CM2250	2883361		
	ISX15 CM2350	4310640		
	X15 X114B	5411182		
	X15 X116B	5411187		

Document History

Date	Details
2017-3-6	Module Created

Last Modified: 17-Mar-2017
