



Technical Service Bulletin

Technical Service Bulletin: TSB170070

Released Date: 12-Jun-2017

Adhesive Aftertreatment Main Body Gasket

Adhesive Aftertreatment Main Body Gasket

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- B6.7 CM2350 B121B
- L9 CM2350 L116B
- X15 CM2350 X114B
- X15 CM2350 X116B

Description of Change

This document announces a new adhesive aftertreatment main body gasket.

Reason for Change

A new adhesive gasket has been developed to aid in aftertreatment system assembly. When assembling a horizontal aftertreatment system the gasket can become misaligned and cause exhaust leaks or v-band clamp damage. The adhesive strips will maintain gasket alignment during aftertreatment system assembly.

Service Instruction

Paper backing **must** be removed prior to gasket installation. See Figure 1 below.



Figure 1, New Adhesive Gasket with Paper Backing.

Service Parts Availability

Service parts are available. See Table 1.

Table 1, Service Parts

Product	Existing Part Numbers		New Part Numbers	
	Cummins Emission Solutions™ Part Number	Cummins® Part Number	Cummins Emission Solutions™ Part Number	Cummins® Part Number
B6.7 CM2350 B121B	Q312536	2871772	A057M526	5417860
L9 CM2350 L116B				
X15 CM2350 X114B	A041U496	5304868	A057M527	5417859
X15 CM2350 X116B				

Document History

Date	Details
2017-5-24	Module Created

Last Modified: 12-Jun-2017
