



Technical Service Bulletin: TSB180034

Released Date: 23-Mar-2018

Aftertreatment Diesel Particulate Filter (DPF) Restriction Test Will Not Complete

Aftertreatment Diesel Particulate Filter (DPF) Restriction Test Will Not Complete

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

Engine:

- X15 CM2350 X114B
- X15 CM2350 X116B

Engine Serial Number (ESN) Range:

- Prior to 80045948

Issue

Symptom:

- Unable to complete aftertreatment diesel particulate filter (DPF) restriction test.

Root Cause:

- A malfunction causes aftertreatment DPF restriction test to abort.

Verification

Aftertreatment DPF restriction test aborts while in progress and will display INSITE™ electronic service tool message: "The test exceeded the maximum amount of time allowed to perform the test before a PASS or FAIL result could be determined".

Resolution

- Calibrate engine control module (ECM) using latest INCAL™ DVD. Reference ECM Calibration Revision History on QuickServe® Online for more information.
- After ECM calibration is complete, perform aftertreatment DPF restriction test. See corresponding Service Manual. Reference Procedure 011-085 in Section 11.
- Verify aftertreatment DPF restriction test has successfully completed.

Document History

Date	Details
2018-3-22	Module Created

Last Modified: 23-Mar-2018
