



Technical Service Bulletin

Technical Service Bulletin: TSB180056

Released Date: 08-May-2018

INSITE Electronic Service Tool Image Aftertreatment Regeneration Temperature History Incorrect

INSITE Electronic Service Tool Image Aftertreatment Regeneration Temperature History Incorrect

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- X15 CM2350 X114
- X15 CM2350 X116
- L9 CM2350 L116
- L9 CM2350 B120C
- B6.7 CM2350 B121
- B6.7 CM2350 B141
- B6.7 CM2350 B136C

Issue

INSITE™ electronic service tool Image Regeneration History Log, located in Advanced ECM Data: Aftertreatment History, is incorrectly recording “Maximum Diesel Particulate Filter Intake Temperature”.

The recorded value is lower than actual temperature and is **not** to be used to diagnose effectiveness of the aftertreatment diesel oxidation catalyst (DOC).

Resolution

An engine control module (ECM) calibration code is being developed to resolve this issue.

Document History

Date	Details
2018-5-8	Module Created

