



Technical Service Bulletin: TSB190190

Released Date: 17-Dec-2019

Aftertreatment Selective Catalytic Reduction (SCR) Cracked/Broken Outlet Flange

Aftertreatment Selective Catalytic Reduction (SCR) Cracked/Broken Outlet Flange

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- X15 CM2350 X114B
- X15 CM2350 X116B

Issue

Symptom:

- An exhaust leak is present on the outlet of the aftertreatment selective catalytic reduction (SCR) outlet flange.

Root Cause:

- Cracking or breakage of the aftertreatment SCR catalyst outlet flange.

Verification

Inspect the aftertreatment SCR outlet for cracks or breakage.

See Figures 1 and 2 below for examples of cracked/broken outlet of the aftertreatment SCR catalyst.

Resolution

If the aftertreatment SCR catalyst outlet flange is cracked or broken; replace the aftertreatment SCR catalyst. See corresponding Service Manual. Reference Procedure 011-036 in Section 11.

Do **not** weld or modify the aftertreatment system to correct the malfunction.

Part Identification



Figure 1, Cracked Aftertreatment SCR Catalyst Outlet Flange.



Figure 2, Broken Aftertreatment SCR Catalyst Outlet Flange.

Date	Details
2019-11-7	Module Created
2019-12-16	Non-Product Problem Solving (PPS)

Last Modified: 17-Dec-2019
