



Technical Service Bulletin

Technical Service Bulletin: TSB190208

Released Date: 03-Dec-2019

Navistar X15 FC 3558

Navistar X15 FC 3558

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Information Only - OEM Related Matter Not Covered By Cummins® - Contact Appropriate OEM Dealer or OEM Representative For Additional Information

Contents

Product Affected

Engines:

- X15 CM2350 X114B
- X15 CM2350 X116B

Original Equipment Manufacturer (OEM):

- Navistar®

Issue

Symptom:

- Fault Code 3558.

Root Cause:

- Improper voltage sense wire placement can cause an interference in the ground supply circuit for the entire powertrain wiring harness, which may result in instances of Fault Code 3558.

Resolution

- Reference IK0800555 in Navistar® Service Portal.

Document History

Date	Details
2019-11-26	Module Created

