



Technical Service Bulletin

Technical Service Bulletin: TSB210054

Released Date: 08-Nov-2021

False Occurrences of Fault Code 555 and 556

False Occurrences of Fault Code 555 and 556

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2450 X124B
- X15 CM2450 X134B

Issue

False occurrences of Fault Code 555 or 556.

Symptom:

- Fault Code 555 or 556 is active or has more than one inactive count within the last 25 engine operating hours

Root Cause:

- Engine control module (ECM) calibration code

Verification

- Compare the ECM calibration code and revision number in the ECM to the ECM calibration revision listed in the ECM calibration revision history on QuickServe® Online (QSOL) for applicable changes.

Resolution

- If an ECM calibration code update for this fault code is available, the ECM calibration code revision **must** be that revision or higher. Update ECM calibration as necessary. See corresponding Service Manual. Reference Procedure 019-032 in Section 19.

Document History

Date	Details
2021-3-3	Module Created
2021-11-4	Added X15 CM2450 X124B and X15 CM2450 X134B.

Last Modified: 08-Nov-2021
