



Technical Service Bulletin: TSB170099

Released Date: 03-Apr-2024

New Engine Oil Pressure Sensor

New Engine Oil Pressure Sensor

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- X15 CM2350 X114B
- X15 CM2350 X116B
- L9 CM2350 L116B
- L9 CM2350 L119B
- L9 CM2350 L123B

Description of Change

A more robust oil pressure sensor has been released.

Reason for Change

New engine oil pressure sensor is more robust.

Customer Communication

If existing engine oil pressure sensor has malfunctioned, Cummins Inc. recommends new engine oil pressure sensor be installed. See Table 1 below for part number information.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Engine Oil Pressure Sensor	4358810	No	No	4921517

Document History

Date	Details
2017-9-11	Module Created
2019-8-13	Added L9 engines.
2019-8-13	Added engine data.
2020-1-23	Added necessary products to Product Affected list.
2024-2-6	Removed unnecessary products from Product Affected list. Updated table 1 to include additional engine oil pressure sensor.
2024-4-3	Removed obsoleted part information from table.

Last Modified: 03-Apr-2024
