



Technical Service Bulletin

Technical Service Bulletin: TSB190185

Released Date: 29-Jan-2020

Fault Code 197 – Intermittent Low Coolant Indicator - PACCAR

Fault Code 197 – Intermittent Low Coolant Indicator - PACCAR

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Information Only - OEM Related Matter Not Covered By Cummins® - Contact Appropriate OEM Dealer or OEM Representative For Additional Information

Contents

Product Affected

- X15 CM2350 X114B
- X15 CM2350 X116B

Issue

A PACCAR TIB has been published to help address intermittent engine Fault Code 197 experiences.

Symptom:

- CEL illuminates intermittently, Fault Code 197.

Root Cause:

- Internal wire fractures on wiring leading to low coolant sensor.
- Improper fill level of coolant overflow tank.

Resolution

Reference PACCAR TIB 42-058.

Document History

Date	Details
2019-10-31	Module Created

Date	Details
2020-1-28	Non-Product Problem Solving (PPS)

Last Modified: 29-Jan-2020
