



Technical Service Bulletin: TSB260122

Released Date: 18-Aug-2026

New Variable Geometry Turbocharger (VGT) Actuator Kits

New Variable Geometry Turbocharger (VGT) Actuator Kits

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- B6.7 CM2350 B121B
- B6.7 CM2350 B135B
- B6.7 CM2350 B136C
- B6.7 CM2350 B148B
- B6.7 CM2350 B157C
- B6.7 CM2450 B155B
- ISB6.7 CM2350 B101
- ISB6.7 CM2350 B103
- ISB6.7 CM2350 B142
- ISL9 CM2350 L101
- ISL9 CM2350 L111
- L9 CM2350 L116B
- L9 CM2350 L119B
- L9 CM2350 L120C
- L9 CM2350 L123B
- L9 CM2350 L129C
- L9 CM2350 L133C
- L9 CM2450 L126B
- QSB6.7 CM2350 B105
- QSB6.7 CM2350 B112
- QSB6.7 CM2350 B130
- QSB6.7 CM2350 B145
- X12 CM2350 X119B
- X12 CM2450 X137B
- X15 CM2350 X114B
- X15 CM2350 X116B

- X15 CM2450 X124B
- X15 CM2450 X134B

Description of Change

New Variable Geometry Turbocharger (VGT) actuator service kits are available in a multipart supersession.

Service Instructions

- See Table 1 for applicable service kit, if needed.
- Parts may be available in RX, PX, H, HX, or NX.
- See Technical Service Bulletin, Incorrect Variable Geometry Turbocharger (VGT) Actuator Kit Part Number: Navistar®, TSB190153 for Navistar® ISB6.7 CM2350 B101 repairs.
- Correct setting of the turbocharger sector gear during installation is critical to proper operation. See corresponding Service Manual. Refer to Procedure 010-134 in Section 10.
- Variable geometry turbocharger actuator part number in kit can deviate from bill of material but is confirmed to be backwards compatible.
- X12 12-Volt applications **must** order a banjo bolt, Part Number 3924725, with service kit, Part Number 6476157. See Technical Service Bulletin, New Variable Geometry Turbocharger (VGT) Actuator and Banjo Bolt, TSB250045.

Service Parts

Service parts are offered.

See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number	Certified Applications
Turbocharger Actuator Kit	5452688	Y	Y	6628262	On-Highway B6.7
				6567567	Off-Highway B6.7
Turbocharger Actuator Kit	5603776	Y	Y	6628244	On-Highway B6.7 On-Highway L9
Turbocharger Actuator Kit	5603777	Y	Y	6628262	On-Highway B6.7
Turbocharger Actuator Kit	6382091	Y	Y	6628263	On-Highway B6.7 On-Highway L9
				6567568	Off-Highway B6.7 Off-Highway L9

Table 1, Service Parts					
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number	Certified Applications
Turbocharger Actuator Kit	6382093	Y	Y	6476157	12 volt X12 CM2350 X119B 12 volt X12 CM2450 X137B See TSB250045 for X12 X15 CM2350 X114B, X15 CM2350 X116B, X15 CM2450 X124B, and X15 CM2450 X134B
Turbocharger Actuator Kit	6382095	Y	Y	6628244	On-Highway B6.7 On-Highway L9
				6567568	Off-Highway B6.7 Off-Highway L9
Turbocharger Actuator Kit	6382096	Y	Y	6628260	On-Highway B6.7
				6567567	Off-Highway B6.7
Turbocharger Actuator Kit	6476161	Y	Y	6628260	On-Highway B6.7
Turbocharger Actuator Kit	6476162	Y	Y	6628262	On-Highway B6.7
Turbocharger Actuator Kit	6476163	Y	Y	6628263	On-Highway B6.7
					On-Highway L9
Turbocharger Actuator Kit	6473311	Y	Y	6567567	Build Date Year 2024 or newer B6.7
Part Inventory Action					

Use existing part number inventory before using the new part number.

Document History

Date	Details
2026-8-18	Module Created

Last Modified: 18-Aug-2026