

Manual Change History (4332828) Marine C Command HD Elite™

Panel System Master Repair Manual

Date	28-Mar-2018
Section	Back
Procedure Number	4332828-history (/qs3/pubsys2/xml/en/manual/4332828/4332828-history.html)
Procedure Title	Manual Change History
Update Reason	New manual for Marine C Command HD Elite™ Panel System released for use.

Date	17-May-2019
Section	Section 15 - Instruments and Controls - Group 15
Procedure Number	300-015-023 (/qs3/pubsys2/xml/en/procedures/300/300-015-023.html)
Procedure Title	Customer Interface Box
Update Reason	Added informaation for the Push Style Terminal Strip.

Date	17-May-2019
Section	Section 15 - Instruments and Controls - Group 15
Procedure Number	300-015-093 (/qs3/pubsys2/xml/en/procedures/300/300-015-093.html)
Procedure Title	Engine Interface Wiring Harness
Update Reason	Added to outline.

Date	17-May-2019
Section	Section 15 - Instruments and Controls - Group 15
Procedure Number	300-015-172 (/qs3/pubsys2/xml/en/procedures/300/300-015-172.html)
Procedure Title	Redundant Power Selector
Update Reason	Added to outline.

Date	21-May-2019
Section	Section F - Familiarization
Procedure Number	300-209-001 (/qs3/pubsys2/xml/en/procedures/300/300-209-001.html)
Procedure Title	System Description
Update Reason	Added information for the Diesel Control Unit 410E.

Date	21-May-2019
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	300-t02-1021 (/qs3/pubsys2/xml/en/procedures/300/300-t02-1021.html)
Procedure Title	Droop Adjust Signal Malfunctions
Update Reason	Added reference to X15 CM2350 X125M Fault Code Troubleshooting Manual, Bulletin 5504346,

Date	22-May-2019
Section	Section 15 - Instruments and Controls - Group 15
Procedure Number	300-015-047 (/qs3/pubsys2/xml/en/procedures/300/300-015-047.html)
Procedure Title	Final Verification
Update Reason	Added to outline.

Date	22-May-2019
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	300-t02-1022 (/qs3/pubsys2/xml/en/procedures/300/300-t02-1022.html)
Procedure Title	Load Adjust Signal Malfunctions
Update Reason	Added reference to X15 CM2350 X125M Fault Code Troubleshooting Manual, Bulletin 5504346,

Date	22-May-2019
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	300-t02-1023 (/qs3/pubsys2/xml/en/procedures/300/300-t02-1023.html)
Procedure Title	Frequency Bias Signal Malfunctions
Update Reason	Added reference to X15 CM2350 X125M Fault Code Troubleshooting Manual, Bulletin 5504346,

Date	22-May-2019
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	300-t02-1025 (/qs3/pubsys2/xml/en/procedures/300/300-t02-1025.html)
Procedure Title	Engine Only Operates in Droop Mode
Update Reason	Added reference to X15 CM2350 X125M Fault Code Troubleshooting Manual, Bulletin 5504346,

Date	22-May-2019
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	300-t02-1026 (/qs3/pubsys2/xml/en/procedures/300/300-t02-1026.html)
Procedure Title	Engine Only Operates in Idle Mode
Update Reason	Added reference to X15 CM2350 X125M Fault Code Troubleshooting Manual, Bulletin 5504346,

Date	22-May-2019
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	300-t02-1027 (/qs3/pubsys2/xml/en/procedures/300/300-t02-1027.html)
Procedure Title	Engine Only Operates in Rated Mode
Update Reason	Added reference to X15 CM2350 X125M Fault Code Troubleshooting Manual, Bulletin 5504346,

Date	22-May-2019
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	300-t02-1040 (/qs3/pubsys2/xml/en/procedures/300/300-t02-1040.html)
Procedure Title	No SAE J1939 Communication Remote Panel
Update Reason	Added reference to X15 CM2350 X125M Fault Code Troubleshooting Manual, Bulletin 5504346,

Date	22-May-2019
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	300-t02-1061 (/qs3/pubsys2/xml/en/procedures/300/300-t02-1061.html)
Procedure Title	Low Oil Pressure Shutdown Lamp Driver Malfunction
Update Reason	Added reference to X15 CM2350 X125M Fault Code Troubleshooting Manual, Bulletin 5504346,

Date	22-May-2019
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	300-t02-1109 (/qs3/pubsys2/xml/en/procedures/300/300-t02-1109.html)
Procedure Title	Shutdown Unit Buzzer Does Not Activate With Fault
Update Reason	Added reference to X15 CM2350 X125M Fault Code Troubleshooting Manual, Bulletin 5504346,

Date	22-May-2019
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	300-t02-1110 (/qs3/pubsys2/xml/en/procedures/300/300-t02-1110.html)
Procedure Title	Shutdown Unit Buzzer Activates Without Fault
Update Reason	Added reference to X15 CM2350 X125M Fault Code Troubleshooting Manual, Bulletin 5504346,

Date	22-May-2019
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	300-t02-1141 (/qs3/pubsys2/xml/en/procedures/300/300-t02-1141.html)
Procedure Title	Control Panel Configured Incorrectly
Update Reason	Added reference to X15 CM2350 X125M Fault Code Troubleshooting Manual, Bulletin 5504346,

Date	22-May-2019
Section	Section 15 - Instruments and Controls - Group 15
Procedure Number	300-022-001_15 (/qs3/pubsys2/xml/en/procedures/300/300-022-001_15.html)
Procedure Title	Service Tools
Update Reason	Added Electronic Service Tool Software Kit, Part Number 3886388 and corrected 5299899 tool number.

Date	22-May-2019
Section	Section L - Service Literature
Procedure Number	300-205-001 (/qs3/pubsys2/xml/en/procedures/300/300-205-001.html)
Procedure Title	Additional Service Literature
Update Reason	Added reference to X15 CM2350 X125M manuals.

Date	09-Jul-2019
Section	Section E - Engine Systems Identification
Procedure Number	300-208-002 (/qs3/pubsys2/xml/en/procedures/300/300-208-002.html)
Procedure Title	Component Diagrams
Update Reason	Added to manual.

Date	19-Jul-2019
Section	Section 1 - Operating Instructions
Procedure Number	300-101-999 (/qs3/pubsys2/xml/en/procedures/300/300-101-999.html)
Procedure Title	Operating Instructions - Overview
Update Reason	Added information for the Diesel Control Unit 410E.

Date	22-Jul-2019
Section	Section E - Engine Systems Identification
Procedure Number	300-208-001 (/qs3/pubsys2/xml/en/procedures/300/300-208-001.html)
Procedure Title	Component Identification
Update Reason	Added information for the Diesel Control Unit 410E.

Date	22-Jul-2019
Section	Section 1 - Operating Instructions
Procedure Number	300-101-013 (/qs3/pubsys2/xml/en/procedures/300/300-101-013.html)
Procedure Title	General Operating Instructions
Update Reason	Added information for the use of a Redundant Power Selector instead of a power switch relay.

Date	22-Jul-2019
Section	Section 19 - Electronic Controls - Group 19
Procedure Number	99-019-361 (/qs3/pubsys2/xml/en/procedures/99/99-019-361.html)
Procedure Title	Component Connector and Pin Inspection
Update Reason	Added to outline.

Date	17-Sep-2019
Section	Section 15 - Instruments and Controls - Group 15
Procedure Number	300-015-172 (/qs3/pubsys2/xml/en/procedures/300/300-015-172.html)
Procedure Title	Redundant Power Selector
Update Reason	Updated the Install section. Added a table for identifying redundant power selector pin numbering.

Date	15-Oct-2019
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	300-t02-1128 (/qs3/pubsys2/xml/en/procedures/300/300-t02-1128.html)
Procedure Title	Redundant Power Selector Malfunction Low Voltage
Update Reason	Added TT tree to master repair manual.

Date	15-Oct-2019
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	300-t02-1129 (/qs3/pubsys2/xml/en/procedures/300/300-t02-1129.html)
Procedure Title	Redundant Power Selector Malfunction Primary Power Malfunction
Update Reason	Added TT tree to master repair manual.

Date	15-Oct-2019
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	300-t02-1130 (/qs3/pubsys2/xml/en/procedures/300/300-t02-1130.html)
Procedure Title	Redundant Power Selector Malfunction No Voltage
Update Reason	Added TT tree to master repair manual.

Date	15-Oct-2019
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	300-t02-1131 (/qs3/pubsys2/xml/en/procedures/300/300-t02-1131.html)
Procedure Title	Redundant Power Selector Secondary Power Malfunction
Update Reason	Added TT tree to master repair manual.

Date	04-Oct-2021
Section	Section 1 - Operating Instructions
Procedure Number	300-101-013 (/qs3/pubsys2/xml/en/procedures/300/300-101-013.html)
Procedure Title	General Operating Instructions
Update Reason	Made note in procedure that in PS107 applications, the shutdown override function is available through the Diesel Control Unit (DCU) and Engine Control Module (ECM).
Date	04-Oct-2021
Section	Section E - Engine and System Identification
Procedure Number	300-206-001 (/qs3/pubsys2/xml/en/procedures/300/300-206-001.html)
Procedure Title	System Identification
Update Reason	Corrected caption for graphic shown in procedure.
Date	04-Oct-2021
Section	Section 1 - Operating Instructions
Procedure Number	300-101-999 (/qs3/pubsys2/xml/en/procedures/300/300-101-999.html)
Procedure Title	Operating Instructions - Overview
Update Reason	Made note in procedure that in in C Command HD Elite Marine Panel System PS107 applications, the shutdown override function is available through the Diesel Control Unit (DCU) and Engine Control Module (ECM).
Date	04-Oct-2021
Section	Section F - Familiarization
Procedure Number	300-209-001 (/qs3/pubsys2/xml/en/procedures/300/300-209-001.html)
Procedure Title	System Description
Update Reason	Added information for C Command HD Elite™ Marine panel system PS107 into procedure.

Date	11-Oct-2021
Section	Section E - Engine and System Identification
Procedure Number	300-344-003 (/qs3/pubsys2/xml/en/procedures/300/300-344-003.html)
Procedure Title	Cummins® Product Technology
Update Reason	Added to manual.
Date	04-Feb-2022
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	300-t02-1117 (/qs3/pubsys2/xml/en/procedures/300/300-t02-1117.html)
Procedure Title	Fuel Leakage Switch Signal Malfunction
Update Reason	Added reference to procedure 019-150 in Step 2D.
Date	04-Feb-2022
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	300-t02-1122 (/qs3/pubsys2/xml/en/procedures/300/300-t02-1122.html)
Procedure Title	Coolant Pressure Signal Malfunction
Update Reason	Added reference to procedure 019-016 in Step 2D.
Date	04-Feb-2022
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	300-t02-1123 (/qs3/pubsys2/xml/en/procedures/300/300-t02-1123.html)
Procedure Title	Sea Water Pressure Signal Malfunction
Update Reason	Added reference to procedure 019-452 in Step 2D.

