

Manual Change History (4358369) QSZ13 CM2150 Z102 Service Manual

Date	24-Jun-2014
Section	Back
Procedure Number	4358369-history (/qs3/pubsys2/xml/en/manual/4358369/4358369-history.html)
Procedure Title	Manual Change History
Update Reason	New manual QSZ13 CM2150 Z102 engine released for use.

Date	09-Apr-2015
Section	Section 8 - Cooling System - Group 08
Procedure Number	269-008-018-tr (/qs3/pubsys2/xml/en/procedures/269/269-008-018-tr.html)
Procedure Title	Cooling System
Update Reason	Added directions to allow the engine to cool before draining coolant.

Date	13-Nov-2015
Section	Section 0 - Product - Group 00
Procedure Number	269-000-017 (/qs3/pubsys2/xml/en/procedures/269/269-000-017.html)
Procedure Title	Engine Barring
Update Reason	Added to outline.

Date	13-Nov-2015
Section	Section 9 - Drive Units- Group 09
Procedure Number	269-009-035 (/qs3/pubsys2/xml/en/procedures/269/269-009-035.html)
Procedure Title	Engine Barring Device
Update Reason	Removed from outline.

Date	14-Jul-2016
Section	TF - Troubleshooting Symptoms (New Format)
Procedure Number	105-t02-1005 (/qs3/pubsys2/xml/en/procedures/105/105-t02-1005.html)
Procedure Title	Vibration Excessive
Update Reason	Revised troubleshooting for brake adjustment, engine mounts, front end belt drive accessories, and vibration damper.
Date	15-Dec-2016
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	269-001-055 (/qs3/pubsys2/xml/en/procedures/269/269-001-055.html)
Procedure Title	Gear Train Backlash, Front
Update Reason	Updated the gear backlash tolerences.
Date	05-Dec-2016
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	00-ttecm (/qs3/pubsys2/xml/en/procedures/00/00-ttecm.html)
Procedure Title	ECM - No Communication Troubleshooting Tree
Update Reason	Modified Steps 2, 6, 9 and 11 and added information for new INLINE™ 7 data link.
Date	22-Mar-2017
Section	Section V - Specifications
Procedure Number	269-018-023 (/qs3/pubsys2/xml/en/procedures/269/269-018-023.html)
Procedure Title	Engine Testing
Update Reason	Updated specifications for used engines.

Date	28-Nov-2017
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	269-003-004-tr (/qs3/pubsys2/xml/en/procedures/269/269-003-004-tr.html)
Procedure Title	Overhead Set
Update Reason	Updated the Valve Adjustment Specifications.
Date	21-Oct-2019
Section	Section 19 - Electronic Controls - Group 19
Procedure Number	105-019-032 (/qs3/pubsys2/xml/en/procedures/105/105-019-032.html)
Procedure Title	Engine Control Module Calibration Code
Update Reason	Added the following statement to the Preparatory Steps of the procedure: "Verify vehicle odometer is equal to the value recorded before ECM removal. Contact OEM service location if values are incorrect."
Date	01-Jul-2020
Section	Section 5 - Fuel System - Group 05
Procedure Number	269-005-236 (/qs3/pubsys2/xml/en/procedures/269/269-005-236.html)
Procedure Title	Fuel System Diagnostics
Update Reason	Corrected torque value listed in the Fuel Pressure Relief Valve Return Flow Test step.
Date	06-Jul-2020
Section	Section 14 - Engine Testing - Group 14
Procedure Number	269-014-004 (/qs3/pubsys2/xml/en/procedures/269/269-014-004.html)
Procedure Title	Engine Run-in (Without Dynamometer)
Update Reason	Added procedure to manual.

Date	14-Jul-2020
Section	Section 14 - Engine Testing - Group 14
Procedure Number	269-014-002 (/qs3/pubsys2/xml/en/procedures/269/269-014-002.html)
Procedure Title	Engine Testing (Chassis Dynamometer)
Update Reason	Added tri-axles and drive axles only.
Date	02-Nov-2022
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	269-012-014-tr (/qs3/pubsys2/xml/en/procedures/269/269-012-014-tr.html)
Procedure Title	Air Compressor
Update Reason	Added Pressure Test steps to procedure.
Date	30-Nov-2022
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	269-002-004-tr (/qs3/pubsys2/xml/en/procedures/269/269-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	Corrected part number listed for one of the plug drivers from 3823372 to 3822372.
Date	23-Feb-2023
Section	Section 5 - Fuel System - Group 05
Procedure Number	269-005-045 (/qs3/pubsys2/xml/en/procedures/269/269-005-045.html)
Procedure Title	Fuel Lift Pump
Update Reason	Added to manual.

Date	09-Sep-2025
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	269-001-054-tr (/qs3/pubsys2/xml/en/procedures/269/269-001-054-tr.html)
Procedure Title	Piston and Connecting Rod Assembly
Update Reason	Updated connecting rod side clearance and minimum/maximum specifications.
Date	09-Sep-2025
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	269-001-005-tr (/qs3/pubsys2/xml/en/procedures/269/269-001-005-tr.html)
Procedure Title	Bearings, Connecting Rod
Update Reason	Updated connecting rod side clearance and minimum/maximum specifications.

Last Modified: 11-Sep-2025
