

Manual Change History (4358379) Cummins® Electronic Throttle and Shift (ETS) and Cummins® Inboard Joystick Marine Controls MC101 Operation and Maintenance Manual

Date	06-May-2014
Section	Back
Procedure Number	4358379-history (/qs3/pubsys2/xml/en/manual/4358379/4358379-history.html)
Procedure Title	Manual Change History
Update Reason	New manual for engine released for use.

Date	05-Sep-2014
Section	Back
Procedure Number	4358379-history (/qs3/pubsys2/xml/en/manual/4358379/4358379-history.html)
Procedure Title	Manual Change History
Update Reason	Phoenix Phase 2.

Date	29-Aug-2019
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4358379-t214-om (/qs3/pubsys2/xml/en/manual/4358379/4358379-t214-om.html)
Procedure Title	Thruster(s) Will Not Respond To Inboard Joystick Operation
Update Reason	Added: If equipped with OEM-supplied thrusters, contact thruster vendor for troubleshooting and repair.

Date	10-Sep-2019
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4358379-t236-om (/qs3/pubsys2/xml/en/manual/4358379/4358379-t236-om.html)
Procedure Title	Lever Control Station/Inboard Joystick Will Not Take Control After Pressing The Station Transfer Button
Update Reason	Cause/Correction added for transparent transfer function configured for control station.
Date	21-Aug-2109
Section	Section 2 - Maintenance Guidelines
Procedure Number	326-102-002-om (/qs3/pubsys2/xml/en/procedures/326/326-102-002-om.html)
Procedure Title	Maintenance Schedule
Update Reason	CIJ/ETS product improvements.

Last Modified: 22-Oct-2019
