

Fault Code: 299

Non-Keyswitch Hot Shutdown

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 299 PID(P): SPN: FMI: Lamp: None SRT:	The engine was shut down by a device other than the keyswitch before proper engine cooldown, resulting in a load factor above the maximum shutdown threshold. Fault Code 299 will be logged if the engine is shut down while hot by the engine protection feature or other OEM devices.	No action is taken by the ECM.

Circuit Description

nonapplicable for this fault code

Component Location

nonapplicable for this fault code

(/qs3/pubsys2/xml/en/procedures/--.html)

Last Modified: 01-Mar-2011
