



Technical Service Bulletin

Technical Service Bulletin: tsb080070	Released Date: 04-Sep-2008
Lubricating Oil Cooler Element Welds	

Lubricating Oil Cooler Element Welds

Core Issue

This Early Field Notification informs the field that Signature™, ISX, and QSX15 lubricating oil cooler elements with the **supplier's** weld marks are acceptable and can be used for repair in the field.

Note : Some lubricating oil cooler elements do not have weld marks and are also acceptable.

Confirmation

All Signature™, ISX, and QSX15 engines are affected.

Observations will be the one or more weld marks from the supplier at any of the four corners of the lubricating oil cooler elements.

There is no failure. Lubricating oil cooler elements welded by the supplier are acceptable.

The standard manufacturing process at the supplier has a high fallout rate. Therefore, in order to meet the volume of demand, while making sure of product quality, some elements are being welded, tested, and supplied to Cummins Inc. for use in production and service. This process is controlled and approved by Cummins Inc. for this supplier **only**. Welding of lubricating oil cooler elements in the field is **not** acceptable.

This is not applicable.

Resolution

Use lubricating oil cooler elements welded at the supplier for repairs in the field. Welding lubricating oil cooler elements in the field is **not** acceptable.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

