



Technical Service Bulletin

Technical Service Bulletin: tsb100386	Released Date: 21-Aug-2006
New Fuel Lift Pump Gasket	

New Fuel Lift Pump Gasket

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin has been superseded by topic 06T5-18. Please see 06T5-18 for fuel lift pump service gaskets used by ISC CM554, QSC8.3 CM554, ISL CM554, QSL9 CM554, Signature, ISX, and QSX15 engines.

Last Modified: 21-Aug-2006
