



Technical Service Bulletin

Technical Service Bulletin: tsb101181	Released Date: 28-Aug-2002
Lubricating Oil Fill Tube	

Lubricating Oil Fill Tube

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic updates the Troubleshooting and Repair Manual, Bulletin 3666239 (</qs3/portal/manualviewer.html?path=/qs3/pubsys2/xml/en/outlines/3666239.html>) with the Lubricating Oil Fill Tube Procedure 007-065 (</qs3/pubsys2/xml/en/procedures/-007-065.html>).

Last Modified: 28-Aug-2002
