



Technical Service Bulletin

Technical Service Bulletin: tsb101227	Released Date: 04-Dec-2002
Part Number Correction to the Cylinder Head Service Tools List	

Part Number Correction to the Cylinder Head Service Tools List

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic provides part number corrections to the valve camshaft bushing installation and removal tool and the injector camshaft bushing installation and removal tool for the Cylinder Head Service Tools page on the Signature, ISX, and QSX15 Series Engines.

Last Modified: 04-Dec-2002
