



Technical Service Bulletin

Technical Service Bulletin: tsb101243	Released Date: 21-Mar-2003
Single-Piece Piston Introduction	

Single-Piece Piston Introduction

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic revises Procedures 010-043, 010-047 and 010-054 in the Signature, ISX, and QSX15 Base Engine Troubleshooting and Repair manual to include single-piece piston information.

Last Modified: 21-Mar-2003
