



Technical Service Bulletin

Technical Service Bulletin: tsb101366

Released Date: 22-Jan-2004

Centinel™ Oil Lines

Centinel™ Oil Lines

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic introduces procedure 007-088 (</qs3/pubsys2/xml/en/procedures/96/96-007-088.html>) and 007-089 (</qs3/pubsys2/xml/en/procedures/96/96-007-089.html>) for Centinel™ Installations.

Related Procedures

96-007-088 (/qs3/pubsys2/xml/en/procedures/96/96-007-088.html)	Centinel™ Oil Lines (/qs3/pubsys2/xml/en/procedures/96/96-007-088.html)
96-007-089 (/qs3/pubsys2/xml/en/procedures/96/96-007-089.html)	Centinel™ Oil Make-Up Tank (/qs3/pubsys2/xml/en/procedures/96/96-007-089.html)

Last Modified: 22-Jan-2004