



# Technical Service Bulletin

---

|                                                 |                            |
|-------------------------------------------------|----------------------------|
| Technical Service Bulletin: tsb101485           | Released Date: 22-Nov-2004 |
| Revised Engine Difficult to Start Symptom Trees |                            |

## Revised Engine Difficult to Start Symptom Trees

### Warranty Statement

---

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

---

This Service/Parts Topic revises the following symptom trees:

- Engine Difficult to Start or Will Not Start (Exhaust Smoke)
- Engine Difficult to Start or Will Not Start (No Exhaust Smoke).

Engine Difficult to Start or Will Not Start (Exhaust Smoke) Engine Difficult to Start or Will Not Start (No Exhaust Smoke)

---

**Last Modified: 22-Nov-2004**

---