



Technical Service Bulletin

Technical Service Bulletin: tsb101636

Released Date: 18-Apr-2005

Lubricating Oil Filter Head Adapter

Lubricating Oil Filter Head Adapter

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic updates the removal of the oil filter head adapter in the event of a loose or missing staking pin in Procedure 007-018 (Lubricating Oil Filter Head Adapter) in the Troubleshooting and Repair Manual Signature, ISX, and QSX15 Engines, Bulletin 3666239.

Note : This is a product improvement and not subject to campaign.

Related Procedures

10-007-018
(/qs3/pubsys2/xml/en/procedures/10/10-007-018.html)

Lubricating Oil Filter Head Adapter
(/qs3/pubsys2/xml/en/procedures/10/10-007-018.html)

Last Modified: 18-Apr-2005