



Technical Service Bulletin

Technical Service Bulletin: tsb101773

Released Date: 29-Nov-2005

Revision to Engine Brake Piston Procedure, Actuator Piston Reuse

Revision to Engine Brake Piston Procedure, Actuator Piston Reuse

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic introduces a revision in the Remove and Inspect for Reuse steps in Procedure 020-019, Engine Brake Piston. The change made is in the event of an actuator piston malfunction on a lever. Replace the lever that contains the malfunctioning actuator piston.

Note : This is a product improvement and is not subject to campaign.

Related Procedures

10-020-019
(/qs3/pubsys2/xml/en/procedures/10/10-020-019.html)

Engine Brake Piston
(/qs3/pubsys2/xml/en/procedures/10/10-020-019.html)

Last Modified: 29-Nov-2005