



Technical Service Bulletin

Technical Service Bulletin: tsb101882	Released Date: 28-Jul-2006
Add Fault Code 72-fc731	

Add Fault Code 72-fc731

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic is adding fault code 72-fc731, Engine Speed Sensor and Camshaft Position Sensor - Mechanical Misalignment Between Camshaft and Crankshaft Sensors. The fault code addition is for the Signature, ISX, and QSX15 engines with CM570.

Engine Speed Sensor and Camshaft Position Sensor - Mechanical Misalignment Between Camshaft and Crankshaft Sensors

Last Modified: 28-Jul-2006
