



Technical Service Bulletin

Technical Service Bulletin: tsb101969

Released Date: 21-Sep-2006

Procedure for Head Casting Erosion Repair

Procedure for Head Casting Erosion Repair

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic introduces a new service kit used to repair cylinder head erosion around the intake ports.

Note : Each kit contains intake port plugs, epoxy filler material, releasing agent, a drill bit, and tool instructions. This kit can be used for multiple repairs, depending on the amount of filler material required.

The kit contains the following:

Cylinder Head Repair Kit, Part Number 4918684

Part Description	Part Number	Quantity
Compound, Metal Repair	4918685	1
Plug, Protective	4918686	3
Drill	4918687	1
Compound, Releasing	4918691	1
Bulletin, Tool Instructions	3400222	1

Related Procedures

35-002-004
(/qs3/pubsys2/xml/en/procedures/35/35-002-004.html)

Cylinder Head
(/qs3/pubsys2/xml/en/procedures/35/35-002-004.html)

Last Modified: 21-Sep-2006

