



Technical Service Bulletin

Technical Service Bulletin: tsb101995

Released Date: 11-May-2010

Fault Code Revisions

Fault Code Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic is revising the following Fault Codes.

- Fault Code 153, Intake Manifold Air Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source.
- Fault Code 195, (3-Wire Sensor) Coolant Level Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source.
- Fault Code 196, (3-Wire Sensor) Coolant Level Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source.
- Fault Code 687, Turbocharger Number 1 Speed Low - Warning Level.
- Fault Code 2551, Fuel System Overfueling.

For Fault Code 153, Fault Code 195, and Fault Code 196, the pin numbers have been corrected to reflect the same pin numbers on the present wiring diagrams for ISX, Signature™, and ISX CM870.

For the Fault Code 687, the turbocharger speed sensor o-ring information was added to the "Shop Talk" section. The addition explains that in some cases the turbocharger original speed sensor o-ring can remain during sensor replacement. The new sensor is then installed with a new o-ring and creates excessive clearance from the sensor to the turbocharger shaft. This can cause fault code 687.

For Fault Code 2551, the direction in step 2A-1 of the troubleshooting procedure for fault code 2551 is misleading. The step has been changed to direct the correct course of action.

Intake Manifold Air Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Engine Coolant Level Sensor Circuit Coolant Level Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Engine Coolant Level Sensor Circuit Coolant Level Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Fuel System Overfueling
Turbocharger Speed Low - Warning Level

Last Modified: 11-May-2010

