



Technical Service Bulletin

Technical Service Bulletin: tsb102043

Released Date: 10-Nov-2006

Revision to Cylinder Head Procedure, Inspect Valve Spring Collet Seating

Revision to Cylinder Head Procedure, Inspect Valve Spring Collet Seating

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Assemble step of Procedure 002-004, Cylinder Head, to add an inspection of the valve spring collet seating.

Related Procedures

10-002-004-tr
(/qs3/pubsys2/xml/en/procedures/10/10-002-004-tr.html)

Cylinder Head
(/qs3/pubsys2/xml/en/procedures/10/10-002-004-tr.html)

Last Modified: 10-Nov-2006