



Technical Service Bulletin

Technical Service Bulletin: tsb102102	Released Date: 18-Dec-2006
Revision, Guided Steps 3C and 3D, Fault Code 2359	

Revision, Guided Steps 3C and 3D, Fault Code 2359

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Fault Code 2359 in the Troubleshooting and Repair Manual, CM870 Electronic Control System, Signature and ISX Engines, Bulletin 4021334. The differential pressure tubes can now be checked for clogs without removing the tubes.

EGR Differential Pressure Sensor - Data Valid But Above Normal Operating Range-Moderately Severe Level

Last Modified: 18-Dec-2006
