



Technical Service Bulletin

Technical Service Bulletin: tsb102142	Released Date: 02-Feb-2007
Revision, Fuel in the Lubricating Oil Symptom Tree	

Revision, Fuel in the Lubricating Oil Symptom Tree

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises symptom tree T092, Fuel in the Lubricating Oil in the Signature, ISX, and QSX15 Service Manual, Bulletin 3666239. The correction for a cracked or porous cylinder head has been updated.

NAME b-092.t

Last Modified: 02-Feb-2007
