



# Technical Service Bulletin

---

|                                                |                            |
|------------------------------------------------|----------------------------|
| Technical Service Bulletin: tsb102151          | Released Date: 26-Feb-2007 |
| Revision, Coolant Loss - Internal Symptom Tree |                            |

## Revision, Coolant Loss - Internal Symptom Tree

### Warranty Statement

---

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

---

This Service/Parts Topic revises symptom tree T021, Coolant Loss - Internal in the Signature, ISX, and QSX15 Service Manual, Bulletin 3666239. The revision adds a step to check the air compressor air inlet and air outlet tubes for signs of coolant and moves the step for pressure testing the cooling system.

NAME b-021.t

---

**Last Modified: 26-Feb-2007**

---