



Technical Service Bulletin

Technical Service Bulletin: tsb102184	Released Date: 21-Mar-2007
Removal, Secondary Step of Guided Step 2, Fault Code 443	

Removal, Secondary Step of Guided Step 2, Fault Code 443

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

The purpose this Service/Parts Topic is to revise Fault code 443, Throttle Voltage Supply, by removing the supply voltage check in Guided Step 2.

Throttle Voltage Supply

Last Modified: 21-Mar-2007
