



Technical Service Bulletin

Technical Service Bulletin: tsb102270	Released Date: 03-May-2007
Addition, Fault Code 951, Bulletin 3666259	

Addition, Fault Code 951, Bulletin 3666259

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

The purpose of the Service/Parts Topic is to add Fault Code 951 to the Troubleshooting and Repair Manual, Electronic Control System, Signature, ISX, and QSX15 Engines, Bulletin 3666259.

Cylinder Power Imbalance

Last Modified: 03-May-2007
