



Technical Service Bulletin

Technical Service Bulletin: tsb102350	Released Date: 23-Jul-2007
Revision, Guided Step 2D, Fault Code 388	

Revision, Guided Step 2D, Fault Code 388

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Guided Step 2D specification for Fault Code 388 in the Troubleshooting and Repair Manual, Electronic Control System, Signature, ISX, and QSX15, Bulletin 3666259.

Engine Brake Supply Circuit

Last Modified: 23-Jul-2007
