



Technical Service Bulletin

Technical Service Bulletin: tsb102504	Released Date: 19-Oct-2007
Revision, Multiple Steps, Fault Codes 297 and 298	

Revision, Multiple Steps, Fault Codes 297 and 298

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic corrects the OEM Pressure Switch circuit illustration and pin numbers for Fault Codes 297 and 298.

OEM Pressure Sensor Circuit OEM Pressure Sensor Circuit

Last Modified: 19-Oct-2007
